

KFNT

Bishop Intl Flint, MI

3.00 mi SW of city N42 57.9283' W83 44.6850' Mag Var: 06W

Nav aids:

Type:	ID:	Freq:	Radial:	Dist:
VORTAC	FNT	116.90	135	0 nm
DME	PSI	111.0	330	18 nm
VORTAC	SVM	114.30	352	34 nm

Traffic Patterns:

Airport Manager:	Aircraft	Altitude (MSL)
	Heavy Aircraft	2280
	Light Aircraft	1582

Runways:

09/27: 7201X150; asphalt, porous friction course, in fair condition; Trees, 540 ft Left of center, 60 ft high, 2,460 ft from end, 37:1 clearance slope; Trees, 98 ft Right of center, 76 ft high, 2,968 ft from end, 36:1 clearance slope;
18/36: 7849X150; asphalt, grooved, in fair condition; Tree, 299 ft Left of center, 79 ft high, 2,229 ft from end, 25:1 clearance slope; Tree, 485 ft Left of center, 69 ft high, 1,945 ft from end, 25:1 clearance slope;


Communication Freqs:

App/Dep 118.8 (;EAST)
App/Dep 128.55 (;WEST)
WX 810-342-7804
ATIS 133.15
CInc-Del 121.75
CLASS C 118.8 (;EAST)
CLASS C 128.55 (;WEST)
CTAF 126.3
Gnd 121.9
Tower 126.3
UNICOM 122.95

Tower: Tower Hrs: 0545-2330

Lights: Actvt MALSR Rys 09 & 27-
CTAF. No Rdo Ctl of Intsty Avbl When
ATCT Clsd; Ry Lgts Preset

Elevation: 782 ft (238.4 m)



Phone: 810-235-6560

Weather: 810-342-7804 (ASOS)

Fees: Landing, Tiedown, Hangar

Charts: NACO: Detroit Sectional

Fuel: 100LL Low-Lead, Jet A

Notes/Remarks:

for Cd When ATCT Clsd, CTC Great Lakes Apch at 269-459-3345. When
Apch Clsd, CTC Cleveland Artcc at 440-774-0490
for Apch/Dep CTC Cleveland Artcc at 440-774-0229 When Great Lakes Apch
Ctl Clsd
Birds and Deer on & Invo of Arpt
Light Aircraft Maintenance on-site: McClellan Aircraft Maintenance
810-767-3940
Security Directive SD-8G

Business Summary

Avflight Flint

Fuel: Unknown-100LL; Unknown-100LL; Unknown-Jet-A
Location: N; Hours: 24/7
Frequencies: Unicom: 122.95; ARINC: 129.15
Phone Number: 810-235-0681

Greater Flint Pilots Association

Location: SE; Hours: 24/7
Phone Number: 810-629-5181



19283
AIRPORT DIAGRAM


AL-618 (FAA)

BISHOP INTL (FNT)
FLINT, MICHIGAN

ATS
133.15
FLINT TOWER ★
126.3 257.9
GND CON
121.9
CLNC DEL
121.75
D

VAR 7.1° W
JANUARY 2015
ANNUAL RATE OF CHANGE
0.0° W

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES
READBCK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.
NOTE: Due to distance of tower from transient ramp,
ATC unable to provide visual guidance or positioning
of aircraft. USE CAUTION.



EC-1, 10 OCT 2019 to 07 NOV 2019

EC-1, 10 OCT 2019 to 07 NOV 2019

19283
AIRPORT DIAGRAM

BISHOP INTL (FNT)
FLINT, MICHIGAN